

FIG. 1.




FIG. 2.




FIG. 9.





FIG. 3.



Sieve Sizes

FIG. 4.




FIG. 5.





FIG. 6.



At various stations (locations) on the road

FIG. 7.




FIG. 8.

FIG. 10.

Thermal Stress & Strength Failure (Spine)
Reference Temperature= -30 C
Spine Fitted

